

## Notice of Network Change – Fort Lauderdale - Coral Ridge, Florida, Central Office Conversion

### Carrier

BellSouth Telecommunications, Inc.  
675 West Peachtree Street NE  
Atlanta, Georgia 30375

**Date Changes are to Occur:** Saturday, March 16, 2002, at 12:01 AM East Standard Time

**Location of Changes:** Fort Lauderdale - Coral Ridge, Florida

**Description of Change Planned:** Fort Lauderdale - Coral Ridge, Florida, 2530 East Oakland Park Blvd. Central Office Conversion - The 1AESS switch (FTLDFLCR56E) will be replaced with a Lucent Technologies – 5ESS Digital switch. The new Common Language Location Identifier (CLLI) for this switch will be FTLDFLCRDS0 and the point code will be 252-046-076. This office is served by the North Dade Golden Glades (NDADFLGG04T) tandem. The following NXX codes will be affected:

**Area Code: 954    NXX: 390, 396, 398, 537, 561, 563, 564, 565, 566, 567, 568, and 630**

**Description of Reasonably Foreseeable Impact of the Planned Change:** Interconnecting carriers with trunk groups to the existing end office will need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide interconnecting carriers with Trunk Group Service Request Forms (TGSRs) that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting carriers planning to submit Access Service Requests (ASRs) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Monday, March 11, 2002, through Tuesday, March 19, 2002. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes or critical dates should be avoided during this period.

**Contact:** Technical questions relating to this change should be directed to: Marcial Canals – Network Ops Plan/Engineer  
6451 North Federal Highway, room 605  
Ft. Lauderdale, FL 33308  
954-928-4533

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or  
780-2171 (FL, GA, NC, SC)  
(If you are calling from a mandatory 10-digit calling area, include your local area code.)

Outside BellSouth region: 1-800-786-7619  
Fax: 1-205-321-2191

**Notice of Network Change Under Rule 51.329(a)**  
**Notification No. SN91082580**  
**Issue Date: September 17, 2001**